

# SYSTEM CONDITION REPORT

## Siemens Somatom Scope

Siemens | Scope | 2014



ecoline

DATE OF ISSUE  
**20.04.2026**

SYSTEM ID  
**REF-3736**

STATUS  
**READY FOR SHIPMENT**

*Certified & Inspected by*  
**Renova Medical Engineering Team**

**RENOVA MEDİKAL**  
**MÜHENDİSLİK TİC. A.Ş.**

Oruçreis Mh. Giyimkent Cd.  
Giyimkent Sitesi No: 86-88  
Esenler / İstanbul

T. 0 850 226 26 22  
F. 0 212 438 48 96

**SYSTEM INFORMATION**

<b>Brand</b>	Siemens
<b>Model</b>	Scope
<b>Y.O.M</b>	2014
<b>Tube Y.O.M</b>	2023
<b>Tube Installation Date</b>	2023
<b>Tube Count(s) (mAs, scansecs, count)</b>	

\* Disclaimer: The technical specifications and status data presented in this report are based on the latest inspection conducted by the Renova Medical Engineering team. All information is subject to final verification.

## SYSTEM PHOTOS



**RENOVA MEDİKAL  
MÜHENDİSLİK TİC. A.Ş.**

Oruçreis Mh. Giyimkent Cd.  
Giyimkent Sitesi No: 86-88  
Esenler / İstanbul

T. 0 850 226 26 22  
F. 0 212 438 48 96